

GR RAPIDS, GERALD R. FORD INT'L (GRR)

FREQ	
ATIS	127.1
TWR/CTAF*	135.65
APP/DEP (R)	
N	124.6
S	128.4
CLNC	119.3
UNICOM	122.95
GND	121.8

8-05 LOCATION

794'
ELEV

09852.A
41-10

G

SKETCH

GRR
twy
sketch
next
pg

RWY 08L/26R	5000' X 100' (1524m X 30m)
RWY 08R/26L	10000' X 150' (3048m X 46m)
RWY 17/35	8501' X 150' (2591m X 46m)

RWY LENGTH BEYOND DISPLACED THR

08R/ — * 08L/ — * 17/ —
26L/ — * 26R/ — * 35/ —

COORDINATES

42° 52.85'N
085° 31.37'W

License
Air Carrier

FM CITY: 6.0 mi SE

LGTT: ROTG BCN, HIRL, MIRL, VASI, REIL.

Aft twr clsd MALSR VASI, PAPI, REIL,
HIRL, MIRL—STD PCL CTAF (When twr
clsd)*.

MGR: James A. Koslosky

Phillip Johnson, Asst

PH: 616-233-6000

616-233-6055 (Aft hrs)

FBO: Rapid Air Svc 616-957-5050,

Northern Air 616-336-4700, 800-262-4953,

Mayday Avionics 616-957-4920

ATND: 24 Hr

● FAA Class "C" Airspace durg *twr opns 0530-2400, otr times Class "E".

● Customs ldg right arpt, ph 616-942-5245.

● Noise abatement procedures in effect.

● Birds on & invof arpt.

● ATIS 616-336-4755.

NAV AIDS: IAP, 115.95 (GRR) 353° 5.8 NM to
fld, ILS.

FUEL: 100LL, JET A

RPR: Major A&P, Avncs

WX: FSS LAN 800-992-7433, ASOS

616-956-3224,

SNW RMVL: Yes

TRNSP: Taxi, Rntl car (at arpt)

MEALS: At arpt


RON: 3.0 mi, CC

GRR, GERALD R. FORD INT'L TAXIWAY

FREQ

ATIS	127.1
ASOS	127.1
TWR/CTAF*	135.65
APP/DEP (R)	
N	124.6
S	128.4
CLNC	119.3
UNICOM	122.95
GND	121.8

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.
 READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.



JULY 1996
 ANNUAL RATE
 OF CHANGE
 6.2W